Notes

- 1. Material is RedLINE.
- This detail illustrates a typical application.Refer to project specific details for more information.
- 3. Prime all EPDM surfaces to receive M1 adhesive before application.



